Fusible PolyMesh
CutAway Stabilizer

- Cut one or more pieces of Fusible PolyMesh CutAway stabilizer approximately 2" larger than your hoop.
- Lay the item to be embroidered wrong side up on an ironing board.
- Place the Fusible PolyMesh CutAway, shiny side down, on the wrong side of the item, centering over the area to be embroidered.
- Press the Fusible PolyMesh CutAway with a medium warm iron.
- CAUTION: Do not overheat.
- For higher stitch count designs, fuse a second layer of Fusible PolyMesh over the first fused layer.
- Hoop the item making sure that the Fusible PolyMesh CutAway completely fills the hooped area.
- HINT: A topper, StitcH2O or Heat2Go, should be used on top of all knits, fleece, terry cloth, and other fabrics with a texture or pile.
- Embroider the item.

  REMOVAL INSTRUCTIONS:
- Remove your embroidered item from the hoop.
- Lay the embroidered item with the stabilizer up on an ironing board.
- If the stabilizer does not easily release when pulled away from the fabric, reheat with a medium warm iron to release the adhesive bond.
- Carefully peel the excess Fusible PolyMesh CutAway from the fabric around the embroidered item until you reach the edges of the stitching.
- Turn the item embroidered side up and, while lifting and folding the embroidered fabric out of the way, carefully trim the Fusible PolyMesh CutAway stabilizer.
- For multiple layers of stabilizer, trim one layer at a time.